

Version info

Firmware for S6500-48MPP6Y(UN) 1.0. This firmware is fully adapted to Omada Pro Controller V1.10.20.

SHA-256 Value:

A9AFCB7DDCA30053C0508D06663C79844A2CB2081C807CFD1F50DAB1A3CDEA8B

SHA-512 Value:

B40C699D2DE45447181F13D6028C9E1A62A9FAEF9C21AE9ACF8D48F65A9C6DEB4AE234C67DE4C65CEEB07104794E26732A8E8C1BC27813BDF42D05D1BF816714

New features

1. Add support for controller adoption through M-LAG member ports.
2. Add support for DAD-v6 in M-LAG.

Enhancements

1. Enhanced stability of stack.
2. Improve fault recovery performance in M-LAG.

Bug fixed

1. Fixed the issue where static IP occasionally be lost after upgrade in controller mode.
2. Fixed the issue where ports fail to link up occasionally after upgrade in controller mode.
3. Fixed the issue where ports fail to link up occasionally under stress testing.
4. Fixed the issue of kernel hang occurring occasionally under stress testing.